For the Performance Grant of 2018-19					
S. No.	Indicators	MoHUA Benchmark	Service Level Benchmarks		
14/~*	Sumbu Samilas		Status 2017-18	Target 2018-19	
1	Coverage of water supply connections	4000/			
2	Per capita supply of water	100%	80	100	
3	Extent of metering of water connections	135 lpcd 100%	100	135	
4	Extent of Non-Revenue Water (NRW)	20%	0	100	
5	Continuity of water supply	24 hours	100 12	100	
6	Quality of water supplied	100%	70	24	
7	Efficiency in redressal of customer complaints	80%	0	100	
8	Cost recovery in water supply services	100%	0	80	
9	Efficiency in collection of water supply related charges	90%	0	100	
	ge management (Sewerage and Sanitation)	30/8	U	90	
1	Coverage of toilets	100%	80	100	
2	Coverage of sewage network services	100%	0	100 0	
3	Collection efficiency of the sewage network	100%	0	30	
4	Adequacy of sewage treatment capacity	100%	0	40	
5	Quality of sewage treatment	100%	0	25	
6	Extent of reuse and recycling of sewage	20%	Ö	55	
7	Efficiency in redressal of customer complaints	80%	Ö	50	
8	Extent of cost recovery in sewage management	100%	0	45	
9	Efficiency in collection of sewerage charges	90%	0	30	
olid	Waste Management				
1	Household level coverage of Solid Waste Management services	100%	57	100	
2	Efficiency of collection of municipal solid waste	100%	20	50	
3	Extent of segregation of municipal solid waste	100%	25	60	
4	Extent of municipal solid waste recovered	80%	40	70	
5	Extent of scientific disposal of municipal solid waste	100%	35	65	
6	Efficiency in redressal of customer complaints	80%	20	70	
7	Extent of cost recovery in SWM services	100%	25	60	
8	Efficiency in collection of SWM charges	90%	30	75	
**********************	Water Drainage			,,,	
1	Coverage of Storm water drainage network	100%	20	50	
2	Incidence of water logging / flooding	0%	25	7	
	For the Performance Grant of 2018-19:	SLB Status of 2017-			
	Coverage of Water Supply (24 X 7) in all Public/Community Toilets	24X7	YES		
2	Percentage of waste being processed scientifically*	100%	50		

